

中華電力有限公司 每月時計空氣質素報告																																
地點：	流浮山															日期：	2023年9月1 - 30日															
監測物：	二氧化硫															單位：	微克/立方米															
時\日	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
00:00	1	5	0	2	2	8	7	10	8	9	9	8	12	9	1	0	--	--	6	3	3	2	4	2	1	0	0	--	3	7		
00:10	1	5	0	2	2	9	8	9	9	9	9	8	11	8	0	0	--	--	6	3	3	2	3	1	2	0	1	--	3	5		
00:20	1	5	0	0	0	8	8	9	8	9	9	9	12	9	0	0	--	--	6	4	3	2	4	2	1	1	2	--	2	5		
00:30	0	4	1	2	1	9	9	9	8	9	9	9	12	8	0	0	--	--	6	4	3	3	3	2	2	1	1	--	1	4		
00:40	0	4	0	1	1	8	9	9	8	9	9	8	12	9	0	0	--	--	6	3	4	2	3	2	3	1	2	--	1	3		
00:50	0	4	1	2	1	8	8	9	9	9	9	9	13	9	1	0	--	--	6	4	3	3	4	3	3	2	2	--	0	5		
01:00	0	4	1	3	2	8	8	9	9	9	9	8	13	8	1	1	--	--	7	4	4	2	3	3	3	1	2	--	2	6		
01:10	0	3	0	1	2	9	8	9	8	8	9	8	13	8	1	1	--	--	7	5	4	2	3	2	3	2	3	--	3	5		
01:20	0	4	0	2	1	9	8	9	9	9	10	9	13	8	1	0	--	--	7	4	4	3	4	3	3	2	2	--	3	4		
01:30	0	3	0	2	1	9	8	9	9	8	10	9	13	8	2	0	--	--	7	5	4	3	4	3	2	2	3	--	3	4		
01:40	1	4	0	2	1	9	9	9	9	9	9	9	13	8	2	0	--	--	6	4	5	4	4	3	4	3	2	--	4	5		
01:50	0	3	0	1	2	10	8	8	8	9	10	9	13	8	1	0	--	--	7	5	4	3	4	4	3	2	3	--	4	5		
02:00	0	4	1	2	2	10	9	9	9	9	10	9	13	8	2	0	--	--	7	5	6	4	4	3	4	3	2	--	5	5		
02:10	1	4	0	2	2	10	8	9	9	9	10	9	13	9	2	0	--	--	7	5	5	3	5	4	4	3	3	--	4	6		
02:20	1	3	1	2	2	9	9	10	9	9	10	9	13	9	2	0	--	--	7	5	6	4	5	4	4	3	3	--	6	6		
02:30	1	4	1	2	2	10	9	9	9	9	10	11	12	9	2	1	--	--	7	5	4	4	5	4	4	3	3	--	5	7		
02:40	0	4	1	3	2	11	9	9	9	9	10	11	12	9	2	0	--	--	7	5	5	4	5	5	4	4	3	--	5	6		
02:50	0	4	1	3	2	11	9	9	9	8	10	11	13	9	2	0	--	--	7	6	5	4	5	4	4	4	4	--	6	6		
03:00	0	3	1	3	3	11	10	10	9	9	10	12	13	9	2	0	--	--	6	5	5	3	5	4	3	4	3	--	6	6		
03:10	1	3	1	3	2	11	8	10	10	8	11	12	12	9	2	0	--	--	7	6	5	4	6	5	4	4	3	--	5	6		
03:20	0	4	1	3	3	10	9	9	9	9	11	12	12	9	2	1	--	--	7	6	5	4	5	4	4	4	3	--	6	7		
03:30	1	4	2	3	3	10	9	9	9	9	10	12	13	9	2	1	--	--	7	6	6	4	6	5	4	4	4	--	6	7		
03:40	1	3	2	2	3	10	10	10	9	9	11	12	13	9	2	0	--	--	7	6	6	5	6	5	4	4	3	--	6	8		
03:50	1	4	2	3	3	10	9	9	9	9	10	12	13	9	2	0	--	--	7	6	6	5	5	5	4	4	3	--	6	7		
04:00	2	4	1	3	3	10	10	10	9	9	11	11	12	9	2	0	--	--	7	6	6	5	5	4	4	4	3	--	7	8		
04:10	1	4	1	3	3	10	9	10	9	9	11	12	13	9	2	0	--	--	7	6	7	5	6	5	5	4	3	--	6	8		
04:20	2	4	1	3	3	10	10	10	9	9	11	12	13	9	2	0	--	--	7	7	6	5	6	5	4	4	4	--	7	8		
04:30	1	3	1	3	3	9	10	9	9	9	10	12	13	8	3	0	--	--	8	7	6	4	6	6	5	3	4	--	7	8		
04:40	1	3	1	3	3	10	10	9	9	9	10	11	12	9	2	0	--	--	8	6	6	5	6	6	5	4	5	--	7	8		
04:50	2	2	1	3	3	10	10	9	10	9	11	12	13	9	2	0	--	--	7	6	6	5	5	6	5	4	4	--	7	8		
05:00	2	2	1	3	3	10	10	8	9	9	10	11	13	9	2	1	--	--	7	6	6	5	5	6	5	4	4	--	7	8		
05:10	2	2	1	3	3	10	10	8	9	9	11	11	13	9	2	0	--	--	7	6	7	5	6	6	4	4	4	--	7	7		
05:20	2	2	2	4	3	10	10	8	9	9	11	11	13	9	2	1	--	--	7	7	7	6	5	5	5	4	4	--	7	8		
05:30	1	3	2	3	3	10	10	9	9	9	10	12	13	9	3	1	--	--	7	7	6	5	5	6	5	4	4	--	7	8		
05:40	2	3	1	4	2	10	10	9	9	9	10	11	13	9	3	1	--	--	7	7	7	5	6	5	6	4	4	--	6	9		
05:50	1	3	1	4	3	10	11	9	9	9	10	12	13	9	2	1	--	--	7	8	7	5	5	6	5	4	3	--	7	8		
06:00	1	3	1	4	3	10	10	9	9	9	10	12	13	9	3	1	--	--	7	7	7	5	5	6	6	4	4	--	7	8</		

中華電力有限公司
每月時計空氣質素報告

地點：流浮山
監測物：一氧化氮

日期：2023年9月1 - 30日
單位：微克/立方米

日\時	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	平均值
1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	2	1	1	1	1	1	1	1	1
3	1	1	1	1	1	1	1	2	2	2	1	1	1	1	1	1	2	2	2	1	2	1	2	1	1
4	1	1	5	13	19	30	40	21	10	6	2	1	1	1	1	1	1	1	1	1	1	2	1	2	7
5	5	3	17	24	17	12	19	8	8	9	5	3	1	1	1	1	1	1	1	1	1	1	1	1	6
6	1	2	1	1	1	1	1	3	4	5	3	3	2	1	1	1	1	1	1	1	1	1	1	11	2
7	11	2	1	2	8	3	5	12	17	23	14	14	6	7	5	6	4	2	2	1	1	1	1	1	6
8	1	1	1	1	1	1	1	1	1	1	1	2	1	1	1	1	2	2	3	3	1	1	1	1	1
9	1	2	1	1	1	1	1	3	2	2	3	3	3	4	3	3	5	4	6	3	4	2	1	1	3
10	1	1	1	1	1	1	1	1	2	2	3	6	5	--	4	4	3	12	24	13	11	1	1	1	4
11	2	2	1	1	1	1	2	4	7	10	9	11	--	4	3	2	2	2	1	1	1	1	2	1	3
12	1	1	1	1	1	2	2	5	7	6	5	7	5	6	6	8	9	9	3	2	3	2	1	1	4
13	1	1	1	1	1	1	4	5	7	5	4	11	10	3	5	7	5	8	1	2	1	1	1	1	4
14	1	1	1	1	1	2	2	18	7	5	5	43	38	14	17	19	5	5	3	3	2	3	3	2	8
15	1	2	2	2	2	2	4	10	8	6	8	6	7	5	5	7	4	2	2	4	4	1	2	6	4
16	2	2	1	1	1	1	4	5	8	7	5	3	3	2	5	3	2	2	1	1	3	1	1	1	3
17	1	1	1	1	2	2	5	7	5	5	3	2	2	2	2	2	4	3	1	2	2	2	2	6	3
18	1	3	4	3	3	3	5	9	7	4	4	5	3	6	8	4	6	7	5	2	2	10	8	7	5
19	20	16	14	11	4	6	20	34	4	5	5	4	12	5	8	7	5	4	2	2	8	7	3	1	9
20	1	1	1	1	1	8	21	12	6	4	3	5	7	8	5	2	5	3	2	2	1	1	2	2	4
21	4	4	2	1	2	4	22	27	9	8	10	6	5	4	3	3	1	1	1	1	1	1	1	1	5
22	1	1	1	1	1	1	5	31	9	3	2	2	2	3	1	0	0	1	1	0	0	0	0	0	3
23	0	2	3	1	1	2	2	4	5	4	3	1	1	1	1	1	1	1	1	1	1	1	0	0	2
24	0	1	1	1	1	1	1	3	3	2	2	1	1	--	1	1	1	1	1	1	1	1	1	1	1
25	1	1	1	1	1	1	2	3	3	2	2	1	1	1	1	1	1	1	1	1	0	0	1	0	1
26	0	0	0	0	0	0	0	1	2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
27	1	1	1	1	1	1	1	2	2	2	1	1	1	1	1	1	2	2	2	1	1	1	1	0	1
28	0	0	1	1	1	1	1	2	3	2	2	1	1	2	2	1	2	1	1	1	1	1	1	0	1
29	0	0	0	0	0	0	1	3	6	3	2	1	1	1	3	3	3	2	1	1	1	1	1	1	1
30	1	1	1	1	1	1	3	5	2	2	1	3	3	2	1	1	1	1	1	1	1	0	0	1	1

備註：
"--" 代表欠缺該段時間的空氣質素數據

中華電力有限公司
每月時計空氣質素報告

地點：	流浮山																日期：	2023年9月1 - 30日							
監測物：	二氧化氮																單位：	微克/立方米							
日\時	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	平均值
1	11	10	12	15	16	13	14	16	15	15	16	18	15	14	14	14	15	15	12	10	8	8	7	7	13
2	7	6	6	6	6	6	6	7	7	8	8	11	9	9	8	8	11	10	11	11	11	11	11	9	8
3	8	9	9	10	9	10	11	12	12	11	9	12	10	8	9	9	17	24	35	31	33	33	58	52	18
4	49	51	53	57	60	58	56	49	38	34	24	20	23	29	32	55	50	48	42	54	28	47	48	45	44
5	50	50	56	56	54	52	52	43	44	43	36	29	24	25	18	18	22	26	28	25	24	28	29	38	36
6	38	49	40	23	28	33	22	23	28	29	30	41	40	23	26	26	38	40	52	35	33	37	38	72	35
7	64	51	35	42	51	42	40	45	47	50	47	48	39	39	38	51	51	41	52	42	28	22	22	20	42
8	16	12	11	14	13	13	12	13	17	16	18	19	15	16	15	14	18	20	28	50	29	24	22	19	19
9	16	14	17	13	12	17	19	24	18	19	23	23	22	32	38	29	38	41	57	53	49	32	26	24	27
10	22	12	11	11	15	13	13	20	20	19	21	21	20	--	25	21	21	39	46	44	38	22	19	20	22
11	23	21	14	14	16	16	16	18	22	21	21	27	--	15	14	10	12	13	16	13	12	17	17	12	17
12	10	13	16	11	8	8	10	11	12	14	13	22	17	22	22	21	28	30	21	23	30	21	11	13	17
13	11	11	10	11	12	12	14	12	12	10	14	35	25	10	21	24	22	29	14	12	9	9	9	8	15
14	6	4	5	5	7	10	13	29	19	21	27	44	43	27	32	36	21	26	29	29	23	29	37	13	22
15	12	21	20	16	19	17	20	18	13	12	17	16	17	14	15	26	26	15	18	36	23	9	15	19	18
16	14	15	7	9	7	12	26	24	21	22	13	14	12	9	20	15	14	14	16	18	15	13	13	11	15
17	11	8	9	11	10	11	16	13	10	10	8	8	6	6	10	9	17	15	24	47	29	28	24	24	15
18	18	29	24	22	22	21	18	13	12	10	11	20	18	22	27	22	29	29	36	26	39	50	44	39	25
19	38	36	35	34	25	23	28	28	9	13	12	16	30	23	28	26	30	31	27	39	51	47	41	28	29
20	28	27	32	25	20	31	32	21	15	15	16	21	23	26	22	16	27	26	33	47	28	25	28	30	26
21	34	31	32	28	23	27	32	32	24	23	27	28	25	29	35	36	24	32	32	52	34	23	21	23	29
22	31	15	16	17	22	29	41	49	28	21	16	29	25	32	31	20	36	54	70	48	25	14	12	11	29
23	19	32	55	9	14	27	20	21	23	17	13	10	9	11	9	10	11	14	13	13	12	11	9	7	16
24	8	9	10	10	10	10	14	14	11	9	7	9	8	--	8	5	6	7	8	12	14	10	9	9	9
25	7	6	6	6	6	8	10	12	11	10	10	12	9	8	8	9	13	11	12	12	11	7	9	10	9
26	7	6	5	5	6	9	11	10	12	11	10	10	7	6	8	8	13	16	16	11	11	10	8	8	9
27	8	6	5	5	6	8	12	12	11	13	10	14	10	9	11	9	23	36	35	32	26	24	18	10	15
28	8	7	7	6	7	8	12	14	12	11	10	12	7	8	10	8	10	12	22	24	19	14	10	8	11
29	7	6	5	6	7	8	14	22	25	12	9	10	8	8	25	24	31	33	34	40	32	31	38	33	20
30	29	12	8	7	15	21	28	23	8	8	8	22	23	17	12	13	14	13	21	26	23	26	34	37	19

備註：

"--" 代表欠缺該段時間的空氣質素數據